

**I-85 SOUTH  
DETOUR ROUTE**

**CMS 1, 5**

MESSAGE NO. 1	MESSAGE NO. 2
RAMP TO I-85 S CLOSED	FOLLOW DETOUR ROUTE

CHANGEABLE MESSAGE SIGN

**CMS 2, 4**

MESSAGE NO. 1	MESSAGE NO. 2
RAMP TO I-85 S CLOSED	DETOUR VIA I-85 N

CHANGEABLE MESSAGE SIGN

**CMS 3**

MESSAGE NO. 1	MESSAGE NO. 2
I-85 S DETOUR	USE EXIT 40

CHANGEABLE MESSAGE SIGN

- NOTES:**
1. PLACE CMS 2 0.5 MILE FROM BOXMEER.
  2. PLACE CMS 1 1 MILE FROM CMS 2.
  3. PLACE CMS 3 0.5 MILE FROM EXIT 40.
  4. PLACE CMS 4 0.25 MILE NORTH OF ATANDO AVE.
  5. PLACE CMS 5 0.5 MILE FROM CMS 4

NOT TO SCALE


APPROVED: *Kenneth C. Thornwell, Jr., P.E.*  
 DATE: 1/8/2020

DocuSigned by:  
Kenneth C. Thornwell, Jr., P.E.  
1E091EF27373405

SEAL  
044089

ENGINEER  
KENNETH C. THORNWELL, JR., P.E.

**DOCUMENT NOT CONSIDERED FINAL  
UNLESS ALL SIGNATURES COMPLETED**



**OFF-SITE  
DETOUR**

**I-85 SOUTH  
RAMP - MAP 19**

I:\8/2020\dot\dfs\root\01NProj\Store\Div\Proj\Division\5905\TrafficControl\TCP\DCNN\I-5905-TC-TMP-IL19Ramp-DeTour.dgn  
 User: jdbaver1