



Curb Ramps To Be Repaired

- Retrofit
- Remove and Replace
- New Curb Ramp
- Remove Ramp

▭ Municipal Boundary
▭ NCHPO Historic Boundary (NR and LHD)

2022 North
WBS: 2021CPT.05.21.20921.1

Old Lead Mine Rd
From SR 1820 To SR 1005

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION 5

Source: NV5 Engineers and Consultants Inc., ESRI, NC OneMap, NCDOT, NCHPO