

PLAN

AS-BUILT REPAIR QU	ANTITY	TABLE
TOP OF DECK REPAIRS		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	606 SQ. YDS.	
CLASS II SURFACE PREPARATION	0.0 SQ. YDS.	
CONCRETE DECK REPAIR FOR PC OVERLAY	0.0 SQ. YDS.	
SHOTBLASTING BRIDGE DECK	606 SQ. YDS.	
PC MATERIALS	54.7 CU. YDS.	
PLACING AND FINISHING PC OVERLAY	606 SQ. YDS.	
GROOVING BRIDGE FLOORS	5021 SQ.FT.	

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2" CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYMER CONCRETE SPECIAL PROVISION.

VALUES REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTION B-B, SEE "JOINT DETAILS" SHEET.

FOR CONCRETE DECK REPAIR FOR PC OVERLAY, SEE SPECIAL PROVISIONS.

FOR PC MATERIALS, SEE SPECIAL PROVISIONS.

APPROX. CLASS II SURFACE PREPARATION

PROJECT NO. I-5746C

MECKLENBURG COUNTY

BRIDGE NO. 590330

SHEET 3 OF 3

SEAL * 35647

8/23/2021

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

RALEIGH

DECK SURFACE REPAIR

SPAN CONTINUE SPAN C

REVISIONS

OCCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS

NO. BY: DATE: NO. BY: DATE: S9-6

1 3 5 TOTAL SHEETS

274

DRAWN BY: REZA KOUCHEKI/ R.L. PUTEK DATE: 07/2021
CHECKED BY: H.A. LOCKLEAR DATE: 07/2021