


Curb Ramps To Be Repaired


- Retrofit
- Remove and Replace
- New Curb Ramp
- Remove Ramp

Municipal Boundary
 NCHPO Historic Boundary (NR and LHD)



2023 N Durham
WBS: 2022CPT.05.12.20321.1

Hamlin Rd
from SR 1632 to SR 1004

 NORTH CAROLINA DEPARTMENT
OF TRANSPORTATION
DIVISION 5

Source: NV5 Engineers and Consultants Inc., ESRI, NC OneMap, NCDOT, NCHPO