

+

+



F.A. PROJECT NO.: NHPIM-0073(054)

NOTES GENERAL DRAWING INFORMATION IS TAKEN FROM THE ORIGINAL PLANS AND THE ROUTINE INSPECTION REPORT DATED 3/4/2020. BRIDGE ORIENTATION CONFORMS TO THE EXISTING BRIDGE PLANS/ROUTINE INSPECTION.

SCOPE OF WORK

PREPARE TOP OF BRIDGE DECK CONCRETE BY SHOTBLASTING METHODS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT. APPLY SILANE DECK TREATMENT. REMOVE EXISTING JOINT MATERIAL AND INSTALL FOAM JOINT SEALS FOR PRESERVATION. REMOVE UNSOUND CONCRETE AND PROPERLY PREPARE EXISTING END BENT AREAS AND PERFORM SHOTCRETE AND/OR CONCRETE REPAIRS.

I HEREBY CERTIFY THAT THIS STRUCTURE WAS REHABILITATED ACCORDING TO THESE PLANS OR AS NOTED HEREIN.

RESIDENT ENGINEER

-DocuSigned by:

Krishna P. Sedar

4150BF4BEARC

ACTION OF ESSION SEAL 031583 PRASAD

10/1/2021

DATE

PROJECT NO. I-5946B RICHMOND COUNTY BRIDGE NO. 760183

> STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> > GENERAL DRAWING

FOR BRIDGE ON I73/74,US22OSBL OVER FIRE TOWER RD.(SR 1455)

	REVISIONS						SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S1-01
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			6