



Map 15 Andrews St SR1915 from Long St SR2100 to concrete joint at US52/I85
 Mill 1 1/2" depth entire width
 Mill 1 1/2" incidental milling at all SR Intersections
 Patching to be done by DOT forces
 Pave 1 1/2" S9.5B

Map 16 Old Union Church Rd SR1915 from concrete joint at US52/I85 to Goodman Lake Rd SR2168
 Mill 0-1 1/2" 7' in width along curb
 Mill 0-1 1/2" incidental milling end, beginning and at all SR intersections
 Patching by contractor
 Asphalt surface treatment, Matcoat, #67m stone
 Pave 1 1/2" S9.5B