NOTES


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.


FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.



PLAN





END BENT 1

DRAWN BY: A. SORSENGINH DATE: 12/2020
CHECKED BY: M. G. SHAIKH DATE: 7/2021

Krishna P. Sedai EA6F794150BF4B7...

SEAL 031583 NGINEER

01/26/2022

PROJECT NO. 15BPR.55

FORSYTH COUNTY
BRIDGE NO. 330227

AS-BUILT REPAIR QUANTITY

END BENT 1

SHOTCRETE REPAIRS

CAP

CURTAIN WALL

CAP

CURTAIN WALL

CAP

TOP OF BENT CAP

CONCRETE REPAIR AREA

SHOTCRETE REPAIR AREA

---- EPOXY RESIN INJECTION (ERI)

EPOXY COATING

EPOXY RESIN INJECTION

CONCRETE REPAIRS

QUANTITIES

ACTUAL

LIN.FT.

SQ.FT.

VOLUME

CU.FT.

VOLUME

CU.FT.

AREA

SQ.FT.

AREA

SQ.FT.

ESTIMATE

AREA

SQ.FT.

1.0

7.2

AREA

SQ.FT.

4.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

VOLUME CU.FT.

0.5

3.6

VOLUME

CU.FT.

LIN.FT.

39.0

3.0

SQ.FT.

142.4

2.0

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

END BENT 1

REVISIONSSHEET NODOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO. BY: DATE: NO. BY: DATE: S2-1613TOTAL SHEETS SHEETS2479

1/25/2022 P:\15BPR55\Structures\Final Plans\402_031_15BPR.55_SMU_ EB1_S16_330227.dgn ksedai