

## STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

ROY COOPER GOVERNOR JAMES H. TROGDON, III Secretary

September 13, 2018

MEMORANDUM TO:	Kelly Coleman Senior Environmental Project Manager ATCS				
	Craig Haden 9/17/2018				
FROM:	Craig Haden 9/17/201 Craig Haden 9/17/201 GeoEnvironmental Project Manager GeoEnvironmental Section Geotechnical Engineering Unit				
TIP NO:	BR-0033				
WBS:	67033.1.1				
COUNTY:	MCDOWELL				
DIVISION	13				
DESCRIPTION:	Bridge # 580084 on SR 1234 over I-40				

SUBJECT:

**Pre-Scoping Comments** 

The GeoEnvironmental Section performed a records search of readily available information for the given project study area to identify known and potential sites of concern. One (1) UST facility was identified within the project area. Refer to the attached table and figures for a list of sites of concern and their anticipated impacts.

A detailed Phase I study of the preferred alternative should be performed to field verify the hazardous waste sites and identify unknown sites. This detailed Phase I study should be included in the environmental document.

cc:

John Pilipchuk, LG, PE, State Geotechnical Engineer Brian Hanks, PE, State Structures Engineer Dale Burton, PE, PLS, State Locations and Surveys Engineer Carl Barclay, PE, State Utilities Manager Randy McKinney, PE, Division Construction Engineer Robert Haskett, Division Right of Way Agent Eric Williams, PE, Geotechnical Regional Manager Jody Kuhne, LG, PE, Regional Geological Engineer Steve Grimes, ROW Unit, Negotiations, State Negotiator row-notify@ncdot.gov roadwaydesign@ncdot.gov

File

Telephone: 919-707-6850 Fax: 919-250-4237 Customer Service: 1-877-368-4968 Location: CENTURY CENTER COMPLEX ENTRANCE B-2 1020 BIRCH RIDGE DRIVE RALEIGH NC

Website: www.ncdot.gov

 Table

 USTs, Landfills & Other Potentially Contaminated Sites of Concern

Site #	Туре	Location	UST Facility ID #	Property Name	Property Owner	Anticipated Impact	Anticipated Risk	Comments
01	UST	121 Parker Padgett Rd Old Fort NC,	00-0- 0000014296, 00-2- 0000014296	Stuckey's Dairy Queen	SH&H Enterprises LLC	Petroleum Contaminated Soil	Low	Currently Stuckey's restaurant and truck stop. Six (6) current USTs. Incident 28642 closed out in 2009.

