

SPAN A

SPAN B

			AS-BUILT REPAIR	QUANTITY	TABLE			
DECK SURFACE REPAIRS - SPAN A		DECK SURFACE REPAIRS - SPAN B			DECK SURFACE REPAIRS - SPAN C			
	ESTIMATE	ACTUAL		ESTIMATE	ACTUAL		ESTIMATE	AC
CLASS II SURFACE PREPARATION	0.0 SQ. YDS.		CLASS II SURFACE PREPARATION	0.0 SQ. YDS.		CLASS II SURFACE PREPARATION	O.O SQ.YDS.	
LATEX MODIFIED CONCRETE OVERALY - EARLY STRENGTH	24.7 CU. YDS.		LATEX MODIFIED CONCRETE OVERALY - EARLY STRENGTH	66.6 CU. YDS.		LATEX MODIFIED CONCRETE OVERALY - EARLY STRENGTH	19.8 CU. YDS.	
PLACING AND FINISHING LMC OVERLAY	390.0 SQ. YDS.		PLACING AND FINISHING LMC OVERLAY	⚠1066.8 SQ. YDS.		PLACING AND FINISHING LMC OVERLAY	316.9 SQ. YDS.	
SCARIFYING BRIDGE DECK	390.0 SQ. YDS.		SCARIFYING BRIDGE DECK	⚠1066.8 SQ. YDS.		SCARIFYING BRIDGE DECK	316.9 SQ. YDS.	
HYDRO-DEMOLITION OF BRIDGE DECK	390.0 SQ. YDS.		HYDRO-DEMOLITION OF BRIDGE DECK	⚠1066.8 SQ. YDS.		HYDRO-DEMOLITION OF BRIDGE DECK	316.9 SQ. YDS.	
GROOVING BRIDGE FLOORS	3329.5 SQ.FT.		GROOVING BRIDGE FLOORS	9042.2 SQ.FT.		GROOVING BRIDGE FLOORS	2652.8 SQ.FT.	

⚠ UPDATED QUANTITES, 4/27/2022

DRAWN BY :	CL BRIGHT	DATE : 06/2019
CHECKED BY :	J.A.TILLMAN	DATE : <u>02/2022</u>

4/27/2022 R:\Structures\FinalPlans\404_009_I5831_SMU_DSR_A_B_C_S4-05_560548.dgn amlee

+

+

SPAN C

S € BENT 2		© JOINT @ END BENT	2
	7		

NOTES

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE. PAYMENT FOR CLASS II SURFACE PREPARATION IS BASED ON THE SQUARE YARD OF ADDITIONAL DEMOLITION REQUIRED FOLLOWING HYDRO-DEMOLITION OF THE BRIDGE DECK. SEE SPECIAL PROVISIONS. FOR SECTION A-A, SEE FOAM JOINT DETAILS SHEET. FOR LMC-ES OVERLAY, SEE SPECIAL PROVISIONS. FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS. FOR BRIDGE JOINT DEMOLITION QUANTITIES, SEE FOAM JOINT DETAIL SHEET.

BRIDGE JOINT DEMOLITION

	PROJECT NO. <u>I-5831A</u>
	MADISON COUNTY
	BRIDGE NO. <u>560548</u>
ACTUAL	SHEET 2 OF 2
NUMBER SOUTHER	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH
SEAL 031021	DECK SURFACE REPAIR SPANS A,B & C
DocuSigned by: MMW MLc B04B5A4F2FAD484 04/27/2022	REVISIONS SHEET NO.
DOCUMENT NOT CONSTDERED	NO. BY: DATE: NO. BY: DATE: S4-05
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	1 3 TOTAL SHEETS 2 4 6