

2/21/2022 R:\Structures\Plans\Bridge_730127\406_017_15BPR56_SMU_DSR1_009_730127.dgn ssandor

+

+

NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

AS-BUILT REPAIR (QUANTIT	Y TABLE
DECK SURFACE REPAIRS - SPANS A THRU D		
	ESTIMATE	ACTUAL
SHOTBLASTING BRIDGE DECK	1,370.4 SQ. YDS.	
SILANE DECK TREATMENT	1,370.4 SQ. YDS.	
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 SQ.FT.	
BRIDGE JOINT DEMOLITION	60.0 SQ.FT.	
DECK SURFACE REPAIRS	- APPROACH	H SLAB 1
	ESTIMATE	ACTUAL
SHOTBLASTING BRIDGE DECK	83.3 SQ. YDS.	
SILANE DECK TREATMENT	83.3 SQ. YDS.	
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 SQ. YDS.	
BRIDGE JOINT DEMOLITION	15.0 SQ.FT.	

	SHOTBLASTING BRIDGE DECK AND SILANE DECK TREATMENT AREA
\sim	ERI - EPOXY RESIN INJECTION
/	BRIDGE JOINT DEMOLITION

RIDGE JOINT DEMOLITION	PROJECT NO. 15BPR.56 PITT COUNTY BRIDGE NO. 730127 SHEET 1 OF 5
B TH CAROL MARTH CAROL MARTH OF ESSION SEAL 26445 CONFERSION	DEPARTMENT OF TRANSPORTATION RALEIGH SUPERSTRUCTURE PLAN OF SPANS
DocuSigned by: P. Korey Newton 4FFE39D1431B407 02/23/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	AND APPROACH SLAB 1 REVISIONS SHEET NO. NO. BY: DATE: NO. BY: DATE: S5-9 1 3 3 55-9 1 3 13