


PENTABLE: xpl_en_v8.tbi
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:34 PM
 FILE: \




8/23/94



PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:34 PM



8/23/2022



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:35 PM
 FILE: \

8/23/2022



150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150



150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150


PENTABLE: xpl_en_v8.tbl
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:35 PM
 FILE: \

150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150




150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150

PLOT DRIVER: NCD01...pdf_color_eng_100.plt
USER: HBARE
DATE: 1/13/2022
TIME: 12:58:35 PM
FILE: \




PLOT DRIVER: NCD01_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:36 PM
 FILE: \



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:36 PM


8/23/94



PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \


DATE: 1/13/2022
 TIME: 12:58:37 PM

8/23/2022




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:37 PM
 FILE: \

8/23/94




PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:38 PM
 FILE: \

8/23/94




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:38 PM
 FILE: \

8/23/2022




PENTABLE: xpl_en_v8.tbl
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:38 PM
 FILE: \



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:39 PM


8/23/2022



PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \


DATE: 1/13/2022
 TIME: 12:58:39 PM


8/23/94




PENTABLE: xpl_en_v8.tbi
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:39 PM
 FILE: \

8/23/94






PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:42 PM
 FILE: \




PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:42 PM
 FILE: \


8/23/2022



PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:43 PM
 FILE: \




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \
 PENTABLE: xpl_en_v8.tbl
 DATE: 1/13/2022
 TIME: 12:58:43 PM



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:43 PM


8/23/2022




PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:44 PM

8/23/94





PENTABLE: xpl_en_v8.tbi
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:44 PM
 FILE: \



PENTABLE: xpl_en_v8.tbi
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:44 PM
 FILE: \


8/23/94

150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150




150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150

PLOT DRIVER: NCD01... PENTABLE: xpl_en_v8.tbl
USER: HBARE DATE: 1/13/2022 TIME: 12:58:45 PM
FILE: \



PENTABLE: xpl_enh_v8.tbl
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:45 PM
 FILE: \


8/23/2022




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:45 PM


8/23/2022




PENTABLE: xpl_en_v8.tb1
 TIME: 12:58:46 PM
 PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 FILE: \




PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:48 PM
 FILE: \



PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:48 PM
 FILE: \




PLOT DRIVER: NCD01.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:48 PM
 FILE: \




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:49 PM

PENTABLE: xpl_en_v8.tbi





PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:49 PM
 FILE: \




PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:50 PM
 FILE: \

150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150





150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150

PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
USER: HBARE
DATE: 1/13/2022
TIME: 12:58:50 PM
FILE: \



PENTABLE: xpl_en_v8.tbl
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:50 PM
 FILE: \


150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150



150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150



PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

PENTABLE: xpl_en_v8.tbi
 TIME: 12:58:51 PM
 DATE: 1/13/2022




PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:53 PM
 FILE: \

150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150



150 140 130 120 110 100 90 80 70 60 50 40 30 20 10 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150


PLOT DRIVER: NCD01...pdf_color_eng_100.plt
USER: HBARE
DATE: 1/13/2022
TIME: 12:58:53 PM
FILE: \



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \


DATE: 1/13/2022
 TIME: 12:58:53 PM

8/23/2022



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \


PENTABLE: xpl_en_v8.tbi
 DATE: 1/13/2022
 TIME: 12:58:54 PM




PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:55 PM

8/23/2022




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:56 PM
 FILE: \




PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:56 PM


8/23/94



PENTABLE: xpl_en_v8.tbl
 PLOT DRIVER: NCD01_pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:57 PM
 FILE: \




PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:57 PM
 FILE: \



PLOT DRIVER: NCDOT_pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:57 PM


8/23/2022



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \


DATE: 1/13/2022
 TIME: 12:58:58 PM

8/23/2022



PLOT DRIVER: NCDOT_color_eng_100.plt
 USER: HBARE
 DATE: 1/13/2022
 TIME: 12:58:58 PM
 FILE: \

8/23/20



PLOT DRIVER: NCD01_.pdf_color_eng_100.plt
 USER: HBARE
 FILE: \

DATE: 1/13/2022
 TIME: 12:58:58 PM

8/23/2022