

NOTES:

GENERAL DRAWING INFORMATION IS TAKEN FROM THE ORIGINAL PLANS AND THE ROUTINE INSPECTION REPORT DATED 1/24/2021. BRIDGE ORIENTATION CONFORMS TO THE EXISTING BRIDGE PLANS AND ROUTINE INSPECTION REPORT.

SCOPE OF WORK

- APPLY DECK SEALANT TO PREPARED TOP OF BRIDGE DECK.

- REMOVE EXISTING JOINT MATERIAL AND INSTALL FOAM JOINTS.

- RESET EXISTING BEARINGS.

- REPAIR PRESTRESSED CONCRETE GIRDERS.

- CLEAN AND EPOXY COAT EXISTING PRESTRESSED CONCRETE GIRDER ENDS.

- REMOVE DEBRIS FROM TOP OF EXISTING END BENTS AND BENT CAPS AND APPLY EPOXY COATING.

- EPOXY RESIN INJECTION OF CONCRETE CRACKS.

- REMOVE UNSOUND AND SPALLED CONCRETE AND PROPERLY PREPARE EXISTING END BENT AND BENT AREAS FOR SHOTCRETE AND CONCRETE REPAIRS.

- REPAIR CONCRETE BARRIER RAIL.

I HEREBY CERTIFY THAT THIS STRUCTURE WAS REHABILITATED ACCORDING TO THESE PLANS OR AS NOTED HEREIN.

RESIDENT ENGINEER

DATE

•		PROJEC	CT NO.	I	-599	7
			WAK	E	CO	UNTY
		BRIDGE NO910242				
SHEET 1 OF 2						
	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH					TION
	Bocusigned by: E i B The CAROL R H CAROL SEAL 020208 MELSON 11/22/2021	GENERAL DRAWING For bridge on 1-440				
	DocuSigned by: Ein Bruch Ja 11/22/2021 ACB8082119D74CD	(CLIFF BENSON BELTLINE) OVER SR 1676 (LAKE BOONE TRAIL)				
venue		REVISIONS SHEET NO.				
3	DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-2
0	FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		<u> </u>		total sheets 82