

+

+

JUMMARI UF QUAI	NTITIES F	FOR SPAN	279
		ESTIMATE	ACTUA
SHOTCRETE REPAIRS (UNDERDEC	.К)	_	
BRIDGE JOINT DEMOLITION		11.0 SF	
CLASS II SURFACE PREPARATI	 ON	-	
CLASS III SURFACE PREPARAT	ION	_	
CONCRETE DECK REPAIR FOR M	MA OVFRLAY	_	
CRACK PRETREATMENT		128.3 LF	
CONCRETE BRIDGE DECK CRACK	SEALTNG	112.0 SY	
MMA OVERLAY SYSTEM	JLALINO	1008.0 SF	
SUMMARY OF QUAN	√ _ <u> </u> ES		
		ESTIMATE	ACTUA
SHOTCRETE REPAIRS (UNDERDEC	- K) 	1.0 CF	
BRIDGE JOINT DEMOLITION		-	
CLASS II SURFACE PREPARATI	ON	-	
CLASS III SURFACE PREPARAT	ION	_	
CONCRETE DECK REPAIR FOR M	MA OVERLAY	_	
CRACK PRETREATMENT		121.9 LF	
CONCRETE BRIDGE DECK CRACK	SEALING	112.0 SY	
MMA OVERLAY SYSTEM		1008.0 SF	
SUMMARY OF QUAN	VITITES	FOR SPAN	281
		ESTIMATE	ACTUA
SHOTCRETE REPAIRS (UNDERDEC	.K)	_	
BRIDGE JOINT DEMOLITION		-	
CLASS II SURFACE PREPARATI	 ON	_	
CLASS III SURFACE PREPARAT	TON	_	
CONCRETE DECK REPAIR FOR M			
CRACK PRETREATMENT		128.3 LF	
CONCRETE BRIDGE DECK CRACK	SEALING	112.0 SY	
MMA OVERLAY SYSTEM		1008.0 SF	
SUMMARY OF QUAN		ENR SPAN	282
JUNIMART OF QUAT			
		ESTIMATE	ACTUA
SHOTCRETE REPAIRS (UNDERDEC	- K)	4.7 CF	
BRIDGE JOINT DEMOLITION		11.0 SF	
CLASS II SURFACE PREPARATI	ON	-	
CLASS III SURFACE PREPARAT	ION	_	
CONCRETE DECK REPAIR FOR M	MA OVERLAY	_	
CRACK PRETREATMENT		137.2 LF	
CONCRETE BRIDGE DECK CRACK	SEALING	112.0 SY	
MMA OVERLAY SYSTEM		1008.0 SF	
SHOTCRETE REPAIRS			
(UNDERDECK) Bridge joint			
	CT NO.	HB-00	17
CLASS II			<u>~ '</u>
DECK REPAIR	DARE	C	OUNT
CLASS III DECK REPAIR DDIDCI		27000	9
MMA	E NO	21000	\cup
OVERLAY SYSTEM			
CRACK PRETREATMENT	STATE OF N	IORTH CAROLINA	
	ARTMENT OF		ATION
WINNTH CAROL	RA	LEIGH	
SFESSION F			
OZOZOB JE SUR	FACE P	REPARA	$\top \bot \bigcirc$
SEAL 020208 SUR		CK RFP	
			$\neg \top \top \land$
	ANS 279	JIHKU	$\angle \heartsuit \angle$
G & Z & A A ZILLION			
Ein Bruch fr 7/14/2022 ACB8082119D74CD			
ACB8082119D74CD	REVISIONS		SHEET
	REVISIONS DATE: NO.	BY: DATE:	SHEET S-S TOTA SHEE