

+

+

AS-BUILT REPA	AIR QU	JANTI	TY TA	TABLE				
BENT 229								
CAP REPAIRS								
SHOTCRETE REPAIRS	1.5 SF	0.8 CF	SF	CF				
EPOXY RESIN INJECTION	_	LF		LF				
PILE REPAIRS								
PILE CONCRETE RESTORATION	154.1 SF	61.9 SF	SF	CF				
FRP PROTECTIVE SYSTEM AWL	384.	5 SF						
FRP PROTECTIVE SYSTEM BWL	99.0) SF						
BENT 230								
CAP REPAIRS								
SHOTCRETE REPAIRS	9.1 SF	4.6 CF	SF	CF				
EPOXY RESIN INJECTION	_	LF		LF				
PILE REPAIRS								
PILE CONCRETE RESTORATION	28.0 SF	11.1 CF	SF	CF				
FRP PROTECTIVE SYSTEM AWL	190.	7 SF						
FRP PROTECTIVE SYSTEM BWL	49.5	5 SF						

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

E	ESTIMATED PILE CRACK QTY. TABLE									
NE SE			NW	W	SW	S	SE	E	NE	Ν
		PILE 1	3	6	_	_	_	_	6	3
NW SW BENT 229	PILE 2	-	-	_	_	_	3	_	_	
	BENT	PILE 3	-	_	_	4	_	_	3	4
	229	PILE 4	6	-	_	13	_	_	_	13
		PILE 5	13	13	_	_	_	13	_	13
		PILE 6	-	6	_	_	-	8	13	-
		PILE 1	_	4	7	8	8	_	6	6
TEM BELOW	BENT	PILE 2	_	_	_	_	_		_	-
.UDE .r mortar	230	PILE 3	3	13		_	_	8	_	3
		PILE 4	3	3	6	3	5	7	7	_
	L Note:For In		n on	PIL	E CO	NDIT		ONLY	 /	
N INJECTION		PROJEC								
		\square	AR				C	OUN	ΛΤΥ	
TIVE SYSTEM			\sim		2-	7 () () ()	~		
ETE RESTORATION	BRIDGE	<u> </u>)			$1 \cup 1$	50	J		
REPAIRS										
STATE OF NORTH CAROLINA					NC					
DEPARTMENT OF TRANSPORTATION RALEIGH DEVENSION BENT 229 & BENT 230 BENT 230										
le	REVISIONS SHEET N					EET NO				
DOCUMENT NOT	CONSIDERED	NO. BY:	DAT	E:	N0.	BY:	D	ATE:		5-284
FINAL UNLE SIGNATURES C	ESS ALL	12			3 4				_	TOTAL SHEETS
		凶			5					355