

+

+

AS-BUILT REPA	PAIR QUANTITY TABLE									
BENT 289										
CAP REPAIRS										
SHOTCRETE REPAIRS	2.6 SF	1.3 CF	SF	CF						
EPOXY RESIN INJECTION	-	LF		LF						
PILE REPAIRS										
PILE CONCRETE RESTORATION	20.3 SF	8.2 CF	SF	CF						
FRP PROTECTIVE SYSTEM AWL	137.	5 SF								
FRP PROTECTIVE SYSTEM BWL	66.0) SF								
BENT 290										
CAP REPAIRS										
SHOTCRETE REPAIRS	- SF	- CF	SF	CF						
EPOXY RESIN INJECTION	-	LF		LF						
PILE REPAIRS										
PILE CONCRETE RESTORATION	28.5 SF	11.1 CF	SF	CF						
FRP PROTECTIVE SYSTEM AWL	148.	5 SF								
FRP PROTECTIVE SYSTEM BWL	66.0) SF								
FOR CAR DEDATES VALUES IN CHART DEDESENT ESTIMATED DEDATE TOTALS										

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2" CL. TO SAWCUT. SEE REPAIR DETAILS. NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE ``TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS'' & ``PILE CONCRETE RESTORATION DETAILS'' SHEETS. FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE ``PILE FRP PROTECTIVE SYSTEM DETAILS'' SHEET.

E	ESTIMATED PILE CRACK QTY. TABLE											
NE/ SE			NW	W	SW	S	SE	E	NE	Ν		
	BENT	PILE 1	6	7	_	_	_	_	4	4		
		PILE 2	6	-	4	6	_	_	3	_		
	289	PILE 3	-	-	-	4	_	_	2	_		
		PILE 4	3	2	3	—	4	4	—	3		
		PILE 1	-	1	1	_	_	1	_	_		
TEM BELOW UDE	BENT	PILE 2	_	6	_	_	4	3	1	_		
R MORTAR	290	PILE 3	_	_	3	_	_	-	3	_		
		PILE 4	5	5	4	2	_	3	7	_		
NOTE: FOR INFORMATION ON PILE CONDITION ONLY.												
PROJECT NO. <u>HB-0017</u>												
N INJECTION			\Box	ΛR	F				\sim L LA	1		
TIVE SYSTEMUARECOUNTY							NIY					
ETE RESTORATION BRIDGE NO. 270009												
REPAIRS												
				0.7.1.7								
DEPARTMENT OF TRANSPORTATION							ЛС					
NUM OR T	RALEIGH											
DEPARTMENT OF TRANSPORTATION RALEIGH DEVARTMENT OF TRANSPORTATION RALEIGH BENT 289 & BENT 290												
DocuSigned by:	BEN		285	18	, X	ВF		2	Y()			
Ein Bhil fr 7/14/2022 ACB8082119D74CD												
le					SIONS					EET NO.		
DOCUMENT NOT		NO. BY:	DAT	E:	NO.	BY:	D	ATE:		5-314 total		
FINAL UNLE SIGNATURES C		1			<u>ড</u> 4				-	total sheets 355		