



Map 3 SR 1917 White Level Rd
 Incidental Mill at Bridge #63 Bridge Approaches
 Do Not Resurface Bridge #63