

DRAWN BY :	ALLEN J.MCSWAIN	DATE : <u>01/2022</u>
CHECKED BY :	FIDEL L.FLORES	DATE : _01/2022_
DESIGN ENGINEER	OF RECORD:	DATE : <u>01/2022</u>

		-
LEGEND		
	CONCRETE REPAIR AREA (CR)	
	SHOTCRETE REPAIR AREA (SCR)	S
	EPOXY RESIN INJECTION (ERI)	

DOCUMENT	NOT	СС
FINAL	UNL	ESS
SIGNATU	res	CON

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL AREA SQ.FT. VOLUME CU.FT. AREA SQ.FT VOLUME CU.FT. SHOTCRETE REPAIRS 6.0 CAP/BACKWALL 2.1 COLUMN/PILE _ _ AREA SQ.FT, AREA SQ.FT. VOLUME VOLUME CU.FT. CONCRETE REPAIRS U.F CAP 12.4 6.5 EPOXY RESIN INJECTION LIN.FT. LIN.FT. 7.6 CAP/BACKWALL COLUMN/PILE _

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1″BEHIND REBAR AND MINIMUM 2″CLEARANCE TO SAWCUT.FOR REPAIR DETAILS,SEE ″CONCRETE RESTORATION DETAILS″ SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS ``SCATTERED THROUGHOUT'' IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >= $\frac{1}{16}$ " AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $1\frac{1}{2}$ "TO 2" ON THE PILES. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

	PROJECT NO. <u>I-5915B</u> <u>CATAWBA</u> county BRIDGE NO. <u>170177</u>		
SHEET 1 OF 4			
Docusigned by SEAL Dicas & Main Market 472972029230445 ATZ972029230445 Dicas & Aguintin A AGUINT A AGUNT A A AGUNT A AGUNT A A AGUNT A A AGUNT A AGUN			
KCA	END BENTS 1 & 2		
KISINGER CAMPO	REVISIONS SHEET NO.		
A S S O C I A T E S ONSIDERED 301 FAYETTEVILLE ST., SUITE 1500	NO. BY: DATE: NO. BY: DATE: S3-8		
S ALL RALEIGH, NC 27601 (919) 882-7839	الال الال الال الال		
MPLETED NC FIRM LICENSE: C-1506	2 4 11		