

AS-BUILT REPAIR QUANT

SUPERSTRUCTURE REPA

| | SPA | SPAN 7 | |
|--------------------------------------------------|----------|--------|--|
| | ESTIMATE | ACTUAL | |
| CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA | 5 EA | | |

* FOR QUANTITIES FOR BEARING REPAIRS, SEE BEARING REPAIR SHEET.



+

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

FOR CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA, SEE SPECIAL PROVISIONS.

FOR BEARING REPAIRS, SEE "BEARING REPAIRS" SHEET.

FOR ZONE PAINTING OF EXISTING STRUCTURE, SEE SPECIAL PROVISIONS.

FOR DETAILS OF CLEANING AND PAINTING GIRDER ENDS (CPG), SEE "MISCELLANEOUS REPAIRS" SHEET.

| DRAWN BY : | ALLEN J.MCSWAIN | DATE : <u>01/2022</u> |
|-----------------|---------------------|-----------------------|
| CHECKED BY : | JACOB H.DUKE | DATE : <u>01/2022</u> |
| DESIGN ENGINEER | OF RECORD:A.AGUIRRE | DATE : <u>01/2022</u> |

4/21/2022 I5915B_SMU_SSR03_480007.dgn daguirre

| TITY | TABLE | |
|------|--------|--------|
| AIRS | | |
| | SPAN 8 | SPAN 9 |

ESTIMATE

-- EA


ACTUAL

ACTUAL

ESTIMATE

-- EA

LEGEND:



PARTIAL PLAN

| DOCUMENT | NC |
|----------|-----|
| FINAL | UI |
| SIGNATU | RES |

