

12/7/2022 R:\Structures\Plans\402_031_15BPR.59_SMU_B01_S2-16_911039.dgn napierce










SUBSTRUCTURE REPAIR QUANTITY TABLE									
BENT 1	QUANTITIES								
	ESTIMATE		ACTUAL						
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF					
САР	0	0							
COLUMN	0	0							
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF					
САР	0	0							
COLUMN	0	0							
EPOXY RESIN INJECTION		LINEAR FT		LINEAR FT					
САР	0	0							
COLUMN		0							
EPOXY COATING		AREA SF		AREA SF					
САР		449.7							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS



UNWRAPPED COLUMN FACE DETAIL

	PROJEC BRIDGE	WAK	E	BPR.5 C0 11039	5 9 UNTY			
SECALISIGNEDARY 037627964 HONOR BERNOLUSION 037627964 HONOR BERNOLUSION 12/08/2022	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIR BENT 1							
	REVISIONS SHEET NO							
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S2-16			
FINAL UNLESS ALL	1		3		TOTAL SHEETS			
SIGNATURES COMPLETED	2		4		18			