

N:\48006-002\CADD\NCDOT\Roadway\Proj\HI-0018\HI-0018\_RDY\_PSH-16.dgn

REMOVE AND REPLACE 2GI REMOVE AND REPLACE 4' OF 15" RCP WITH CONCRETE COLLAR REPLACE CONCRETE APRON SEED AND MULCH DISTURBED AREA ROCK INLET SEDIMENT TRAP TYPE C WATTLES IN DITCH UPGRADE OF INLET PLUG & FILL EXISTING 24" CMP WITH FLOWABLE FILL. CONTAIN GROUT OUTSIDE OF WETLANDS. CONTRACTOR'S MEANS & METHODS SHOULD ASSURE PIPES ARE FLOWABLE FILLED COMPLETELY. 74 76 \_174WBL\_ 870+00 1 (18) 1 (17) -174EBL-875+00 870+00 MM 257 (214) 74 76 the reacher Parts 895,+00 890,+00 -174WBL--I74EBL-895+00 890+00 74 76 915+00 920+00 -I74WBL-–I74EBL– 9/5*+00* 920+00

