

## STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

MICHAEL F. EASLEY
GOVERNOR

Wednesday, June 27, 2007

LYNDO TIPPETT
SECRETARY

**MEMORANDUM TO:** 

Mr. Michael L. Holder, PE

**Division Engineer** 

Division 12

FROM:

L.C. Smith

**GIS Director** 

SUBJECT:

2006 District 3 Road System Changes

The Data Compilation Section has been authorized to make the following changes to the state road system as indicated below. We request that you make similar changes to the related maps and files in your Division and District offices, and install appropriate road number signs if necessary. We have updated our records and county maps accordingly. If our system changes do not conform to the actual conditions in the field, please return this memorandum with recommendations.

<b>Contract Number</b>	County	<b>Approval Date</b>	
8.2790907	CATAWBA	5/15/2006	

Inquires about changes should be referred to one of the following: Ron Tucker (Div 3,6,7,8) at (919) 212-6080, Ron Nealy (Div 5,9,11,13,14) at (919) 212-5980, or Lori Mann (Div 1,2,4,10,12) at (919) 212-6075. If you have further questions, please contact Hardee Cox, Data Compilation Section Manger at (919) 212-6060. Thank you for your assistance.

LCS/hrc enclosures ( )

cc: BSIP

Bridge Maintenance Division Right of Way Pavement Management Permit Unit State Road Maintenance Traffic Engineering Traffic Surveys




FAX: (919) 212-5999

## 2006 ROAD SYSTEM CHANGES

PROJECT NUMBER	COUNTY	APPROVAL DATE	NEW NUMBER	EXISTING NUMBER	STREET NAME	LENGTH (miles)	TYPE OF CHANGE	REMARKS (See Attached Map)
8.2790907	CATAWBA	5/15/2006	SR 3031	SR 1471		0.16	NUMBER REASSIGNMENT VIA PROJECT	MAP , SEGMENT
8.2790907	CATAWBA	5/15/2006	SR 3031			0.07	SYSTEM ADDITION VIA PROJECT	MAP , SEGMENT
8.2790907	CATAWBA	5/15/2006		SR 1471		0.19	SYSTEM DELETION VIA PROJECT	MAP , SEGMENT
8.2790907	CATAWBA	5/15/2006		SR 1471		0.11	SYSTEM ADDITION VIA PROJECT	MAP , SEGMENT
8.2790907	CATAWBA	5/15/2006		SR 1005	9 P	2.25	SYSTEM ADDITION VIA PROJECT	MAP , SEGMENT

## CATAWBA COUNTY

LOCATION: HICKORY – EAST SIDE THOROUGHFARE FROM NORTH OF INTERCHANGE AT I-40 TO NORTH OF SR 1692(TATE BOULEVARD)



NOT TO SCALE

