

## STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BEVERLY EAVES PERDUE

Thursday, February 17, 2011

EUGENE A. CONTI, JR

**MEMORANDUM TO:** Mr. Barry Moose, PE

Division Engineer

Division 10

**FROM:** John C. Farley, Manager

Geographic Information Systems Unit

**SUBJECT:** 2011 District 3 Road System Changes

The Data Conversion Group has been authorized to make the following changes to the state road system as indicated below. We request that you make similar changes to the related maps and files in your Division and District offices, and install appropriate road number signs if necessary. we have updated our records accordingly. If our system changes do not conform to the actual conditions in the field, please return this memorandum with recommendations.

| <b>Document Number</b> | County | <b>Approval Date</b> |  |
|------------------------|--------|----------------------|--|
| U-3412A                | UNION  | 9/22/2010            |  |

Inquiries about changes should be referred to the GIS Help Desk at (919) 707-2152. Thank you for your assistance.

**JCF** 

cc: BSIP

Bridge Maintenance Division Right of Way

IMG

Pavement Management

Permit Unit

State Road Maintenance

Traffic Engineering

Traffic Surveys



## 2011 ROAD SYSTEM CHANGES

| DOCUMENT<br>NUMBER | COUNTY | APPROVAL<br>DATE | NEW<br>NUMBER | EXISTING<br>NUMBER | STREET<br>NAME | LENGTH (miles) | TYPE OF CHANGE                           | REMARKS<br>(See Attached Map) |
|--------------------|--------|------------------|---------------|--------------------|----------------|----------------|--|-------------------------------|
| U-3412A            | UNION  | 9/22/2010        | SR 3514       |                    |                | 0.20           | SYSTEM ADDITION - NEW<br>VIA<br>TIP      | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        | SR 2143       | SR 3172            |                | 0.71           | NUMBER REASSIGNMENT<br>VIA<br>TIP        | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        | SR 2143       | SR 3107            |                | 0.52           | NUMBER REASSIGNMENT<br>VIA<br>TIP        | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        | SR 2143       | SR 1223            |                | 0.44           | NUMBER REASSIGNMENT<br>VIA<br>TIP        | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        | SR 2143       | SR 1158            |                | 0.02           | NUMBER REASSIGNMENT<br>VIA<br>TIP        | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        |               | SR 2143            |                | 0.43           | SYSTEM ADDITION - EXISTING<br>VIA<br>TIP | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        |               | SR 2143            |                | 1.09           | SYSTEM ADDITION - EXISTING<br>VIA<br>TIP | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        |               | SR 1158            |                | 0.14           | SYSTEM DELETION<br>VIA<br>TIP            | MAP , SEGMENT                 |
| U-3412A            | UNION  | 9/22/2010        |               | SR 1158            |                | 0.06           | SYSTEM ADDITION - EXISTING<br>VIA<br>TIP | MAP , SEGMENT                 |

