

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

ROY COOPER
GOVERNOR

JAMES H. TROGDON, III
SECRETARY

DATE: April 13, 2018

TO: Mr. J.D. Jennings, PE

Division Engineer

Division 1

FROM: Mr. John C. Farley, GISP, CPM

Manager

Geographic Information Systems Unit

SUBJECT: 2018 District 3 Road System Changes

The GIS Unit's Data Conversion Group has been authorized to make the changes indicated below to the state road system. We request that you update the related maps and files in your offices and install appropriate road number signs, if necessary. If our system changes do not conform to the actual conditions in the field, please return this memorandum with recommendations.

| Hwy. Ordinance # | County | Approval Date | | |
|------------------|---------|---------------|--|--|
| HTO_089_04-18 | TYRRELL | 4/12/2018 | | |

Questions or comments about changes should be referred to the GIS Help Desk at GISHelp@ncdot.gov. Thank you for your assistance.

JCF

cc: BSIP

Bridge Maintenance Division Right of Way

IMG

Pavement Management

Permit Unit

State Road Maintenance Traffic Engineering

Traffic Surveys

Website: www.ncdot.gov

2018 ROAD SYSTEM CHANGES

| нто | COUNTY | APPROVAL DATE | NEW ROUTE | EXISTING ROUTE | STREET NAME | LENGTH (miles) | TYPE OF CHANGE | REMARKS (See Attached Map) |
|-------------------|---------|------------------|--------------|-------------------|----------------|----------------|-------------------------------|-------------------------------|
| HTO_089_04- 18 | TYRRELL | 4/12/2018 | NC 94 | SR 1112 | | 1.25 | REASSIGNMENT VIA HTO | MAP , SEGMENT |
| HTO_089_04- 18 | TYRRELL | 4/12/2018 | SR 1250 | NC 94 | | 0.11 | REASSIGNMENT VIA HTO | MAP , SEGMENT |
| HTO_089_04- 18 | TYRRELL | 4/12/2018 | SR 1249 | NC 94 | | 0.08 | REASSIGNMENT VIA HTO | MAP , SEGMENT |
| HTO_089_04- 18 | TYRRELL | 4/12/2018 | | NC 94 | | 0.81 | SYSTEM DELETION VIA HTO | MAP , SEGMENT |

Document Number: HTO_089_04-18 Route Number(s): NC-94 1112 1249 1250 Map Date: 04/13/18 **County: Tyrrell** Approval Date: 04/12/18 MC . 94 37 243 Delete NC 94 for 0.81 Mi Reassign NC 94 To SR 1249 for 0.08 Mi Reassign NC 94 To SR 1250 for 0.11 Mi Reassign SR 1112 To NC 94 for 1.25 Mi SR - 1113 SR - 1110 2.208 Legend Addition Deletion Reassignment SR NC US Interstate Ramp Non-System 1,900 475 950 2,850 3,800 Obliterated