

WETLAND DETERMINATION DATA FORM – Eastern Mountains and Piedmont

Project/Site: Bridge 000267 - NES Bridge Group 1 City/County: Alamance County Sampling Date: 04/12/12
 Applicant/Owner: NCDOT State: NC Sampling Point: AB01-U
 Investigator(s): A. Efirid Section, Township, Range: _____
 Landform (hillslope, terrace, etc.): Stream channel Local relief (concave, convex, none): concave Slope (%): 0
 Subregion (LRR or MLRA): LRR P Lat: 36.217452 Long: -79.502307 Datum: NAD83
 Soil Map Unit Name: Appling Sandy Loam, eroding, sloping phase NWI classification: na

Are climatic / hydrologic conditions on the site typical for this time of year? Yes ☒ No _____ (If no, explain in Remarks.)
 Are Vegetation ☐ Soil ☐ or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ☒ No ☐
 Are Vegetation ☐ Soil ☐ or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes ☐ No ☒	Is the Sampled Area within a Wetland? Yes ☐ No ☒
Hydric Soil Present? Yes ☐ No ☒	
Wetland Hydrology Present? Yes ☐ No ☒	
Remarks:	
This form is for all wetlands within the study area. This includes WETLANDS WA and WB.	

HYDROLOGY

Wetland Hydrology Indicators:		Secondary Indicators (minimum of two required)
Primary Indicators (minimum of one is required; check all that apply)		
☐ Surface Water (A1)	☐ Water-Stained Leaves (B9)	☐ Surface Soil Cracks (B6)
☐ High Water Table (A2)	☐ Aquatic Fauna (B13)	☐ Sparsely Vegetated Concave Surface (B8)
☐ Saturation (A3)	☐ True Aquatic Plants (B14)	☐ Drainage Patterns (B10)
☐ Water Marks (B1)	☐ Hydrogen Sulfide Odor (C1)	☐ Moss Trim Lines (B16)
☐ Sediment Deposits (B2)	☐ Oxidized Rhizospheres on Living Roots (C3)	☐ Dry-Season Water Table (C2)
☐ Drift Deposits (B3)	☐ Presence of Reduced Iron (C4)	☐ Crayfish Burrows (C8)
☐ Algal Mat or Crust (B4)	☐ Recent Iron Reduction in Tilled Soils (C6)	☐ Saturation Visible on Aerial Imagery (C9)
☐ Iron Deposits (B5)	☐ Thin Muck Surface (C7)	☐ Stunted or Stressed Plants (D1)
☐ Inundation Visible on Aerial Imagery (B7)	☐ Other (Explain in Remarks)	☐ Geomorphic Position (D2)
		☐ Shallow Aquitard (D3)
		☐ Microtopographic Relief (D4)
		☐ FAC-Neutral Test (D5)
Field Observations:		
Surface Water Present? Yes ☐ No ☒	Depth (inches): _____	Wetland Hydrology Present? Yes ☐ No ☒
Water Table Present? Yes ☐ No ☒	Depth (inches): _____	
Saturation Present? Yes ☐ No ☒ (includes capillary fringe)	Depth (inches): _____	
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		
Remarks:		

VEGETATION – Use scientific names of plants.

Sampling Point: AB01-U

Tree Stratum (Plot size: 15mx15m)	Absolute % Cover	Dominant Species?	Indicator Status	
1. <u>Juniperus virginiana</u>	10%	Yes	FACU	Dominance Test worksheet: Number of Dominant Species That Are OBL, FACW, or FAC: <u>4</u> (A) Total Number of Dominant Species Across All Strata: <u>9</u> (B) Percent of Dominant Species That Are OBL, FACW, or FAC: <u>44%</u> (A/B)
2. <u>Acer rubrum</u>	10%	Yes	FAC	
3. <u>Quercus falcata</u>	10%	Yes	FACU	
4. <u>Ulmus alata</u>	5%	No	FACU	
5. <u>Pinus taeda</u>	5%	No	FAC	
6. _____	_____	_____	_____	
7. _____	_____	_____	_____	
40% = Total Cover				Prevalence Index worksheet: Total % Cover of: _____ Multiply by: _____ OBL species _____ x 1 = _____ FACW species _____ x 2 = _____ FAC species _____ x 3 = _____ FACU species _____ x 4 = _____ UPL species _____ x 5 = _____ Column Totals: _____ (A) _____ (B) Prevalence Index = B/A = _____
Sapling Stratum (Plot size: 15mx15m)				
1. <u>Acer rubrum</u>	10%	Yes	FAC	
2. <u>Ulmus alata</u>	5%	Yes	FACU	
3. <u>Liquidambar styraciflua</u>	5%	Yes	FAC	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
20% = Total Cover				
Shrub Stratum (Plot size: 15mx15m)				Hydrophytic Vegetation Indicators: ___ Dominance Test is >50% ___ Prevalence Index is ≤3.0 ¹ ___ Problematic Hydrophytic Vegetation ¹ (Explain) ¹ Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
_____ = Total Cover				
Herb Stratum (Plot size: 15mx15m)				Definitions of Vegetation Strata: Tree – Woody plants, excluding woody vines, approximately 20 ft (6 m) or more in height and 3 in. (7.6 cm) or larger in diameter at breast height (DBH). Sapling – Woody plants, excluding woody vines, approximately 20 ft (6 m) or more in height and less than 3 in. (7.6 cm) DBH. Shrub – Woody plants, excluding woody vines, approximately 3 to 20 ft (1 to 6 m) in height. Herb – All herbaceous (non-woody) plants, including herbaceous vines, regardless of size. Includes woody plants, except woody vines, less than approximately 3 ft (1 m) in height. Woody vine – All woody vines, regardless of height.
1. <u>Toxicodendron radicans</u>	10%	Yes	FAC	
2. <u>Allium canadense</u>	5%	Yes	FACU	
3. <u>Eupatorium capillifolium</u>	5%	Yes	FACU	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
_____ = Total Cover				
Woody Vine Stratum (Plot size: 15mx15m)				Hydrophytic Vegetation Present? Yes ☐ No ☒
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
5. _____	_____	_____	_____	
_____ = Total Cover				
Remarks: (If observed, list morphological adaptations below).				

SOIL

Sampling Point: AB01-U

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-16	10YR 5/4						SL	Sandy Loam

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators:

- ☐ Histosol (A1)
☐ Histic Epipedon (A2)
☐ Black Histic (A3)
☐ Hydrogen Sulfide (A4)
☐ Stratified Layers (A5)
☐ 2 cm Muck (A10) (LRR N)
☐ Depleted Below Dark Surface (A11)
☐ Thick Dark Surface (A12)
☐ Sandy Mucky Mineral (S1) (LRR N, MRLA 147,148)
☐ Sandy Gleyed Matrix (S4)
☐ Sandy Redox (S5)
☐ Stripped Matrix (S6)

- ☐ Dark Surface (S7) (LRR P, S, T, U)
☐ Polyvalue Below Surface (S8) (MLRA 147,148)
☐ Thin Dark Surface (S9) (MLRA 147, 148)
☐ Loamy Gleyed Matrix (F2)
☐ Depleted Matrix (F3)
☐ Redox Dark Surface (F6)
☐ Depleted Dark Surface (F7)
☐ Redox Depressions (F8)
☐ Iron-Manganese Masses (F12) (LRR N, MLRA 136)
☐ Umbric Surface (F13) (MLRA 136, 122)
☐ Piedmont Floodplain Soils (F19) (MLRA 148)

Indicators for Problematic Hydric Soils³:

- ☐ 2 cm Muck (A10) (MLRA 147)
☐ Coast Prairie Redox (A16) (MLRA 147, 148)
☐ Piedmont Floodplain Soils (F19) (MLRA 136, 147)
☐ Red Parent Material (TF2)
☐ Very Shallow Dark Surface (TF12)
☐ Other (Explain in Remarks)

³Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: _____

Depth (inches): _____

Hydric Soil Present? Yes ☐ No ☒

Remarks: