

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
FIELD SCOPING MEETING WORKSHEET
Design Build Process

WBS No.: **46312.3.F1 (B-5554) (FLAP-0215(7))** Field Scoping Meeting Date: **December 3, 2014**
Division: **14** Location: **On-site**
Route (US/NC/SR): **NC 215** County: **Transylvania**
Project Description: **Bridge No. 870073 over Beetree Fork on NC 215 (Parkway Road)**
Tier: **Regional**
Municipality: **No**

Attendees

	Name	Phone No.	E-mail
Division Bridge Manager	Josh Deyton	828-488-0902	jbdeyton@ncdot.gov
Asst. Bridge Program Mgr.	Mark Hill	828-488-0902	Mehill3@ncdot.gov
Division Environmental Off.	Mark Davis	828-586-2141	markdavis@ncdot.gov
Asst. Div. Env. Officer	Dave McHenry	828-586-2141	dgmchenry@ncdot.gov
Hydraulics Engineer	Marc Shown	919-707-6751	mshown@ncdot.gov
Hydraulics Engineer	Rusty Lassiter	919-707-6732	rlassiter@ncdot.gov
NCDOT – Geotechnical	Shane Clark	282-298-3228	scclark@ncdot.gov
TPMU	Pam Williams	919-707-6608	prwilliams@ncdot.gov
TPMU	Jamie Lancaster	919-707-6620	jlancaster@ncdot.gov
Bridge Management	Paul Garrett	919-707-6457	pgarrett@ncdot.gov
NCDOT – L&S	Pat Tuttle	336-969-9550	ptuttle@ncdot.gov
NCDOT – L&S	Rod McDonald	282-586-0925	rmcdonald@ncdot.gov
NCDOT- L&S	Barry Hamrick	828-586-0925	bhamrick@ncdot.gov
USACE	Lori Beckwith**	828-271-7980 x 223	Loretta.A.Beckwith@usace.army.mil
DENR-DWR	Kevin Barnett**	828-296-4657	Kevin.barnett@ncdenr.gov
USFWS	Jay Mays	828-258-3939 x 226	Jason_mays@fws.gov
NCWRC	Andrea Leslie	828-400-4223	Andrea.Leslie@ncwildlife.org
NCWRC	Marla Chambers	704-485-8291	Marla.chambers@ncwildlife.org
US Forest Service	Karen Compton	828-257-4230	kcompton@fs.fed.us
US Forest Service	Lorie Stroup	828-877-3550 x 219	loriestroup@fs.fed.us
US Forest Service	Dave Danley	828-712-5752	ddanley@fs.fed.us
NC-Cherokee	Tyler Howe**		tylehowe@nc-cherokee.com
FHWA	Mitch Batuzich**		Michael.batuzich@dot.gov

****Invited but could not attend field meeting.**

Existing Features

Feature Bridged: **870073 over Beetree Fork on NC 215 (Parkway Road)**

Ex. Bridge Clear Deck Width: **18.75 (Ft.)** Roadway width: **21 (Ft.)**

(Bridge / Culvert) Length: **35 (Ft.)** Deck Width (Out To Out): **20(Ft.)**

Water Depth: **1(Ft.)** Height Bed-To-Crown: **14(Ft.)**

Year Built: **1936** Posted: SV **Not Posted** TTST: **Not Posted**

Superstructure: **RC Floor on I-Beams** Abutment: **Reinforced Concrete** Pier Type:

Temp. Shored: **N**

Historic High Water (Elev. To The Existing Structure): **(Ft)**

PRI: **29.83** DP: **5.5** SR: **61.4** School Bussing crossings per day: **None**

Posted Speed Limit Vicinity: **55 (mph) statutory**

Detour Off-Site ☐ Stage Construction ☒ New Alignment ☐ On-site ☐

Upstream or downstream

If Off-Site, Description Of Detour Route: **N/A**

Approximate Length Of Detour? **N/A**

Improvements Needed To Road(s) On Detour? **N/A**

Div. Traffic Eng. Recommend Off-site detour signing? **N/A**

Improvements Needed To Bridges On Detour? **N/A**

Are future plans for upgrading this roadway either at or in the vicinity of this project? **No**

Are Bridges On Detour Currently Programmed? **N/A**

Are There EMS Or Business Access Issues? **No**

Are There Any Railroad Crossings On Detour? **No**

Should Work Zone Pedestrian Access Be Maintained During Construction? **No**

Overhead Utility Lines ~~In Conflict~~ **No Utilities**

Power Transmission Lines ~~In Conflict~~

Telephone ~~In Conflict~~

Cable Lines ~~In Conflict~~

Fiber Optic ~~In Conflict~~

Water ~~In Conflict~~

Sewer ~~In Conflict~~

Natural Gas ~~In Conflict~~

Other ~~In Conflict~~

What Is The Estimated Time Required To Complete Utility Adjustments **N/A**

Is There Any Future Utility Construction Anticipated In The Project Area **No**

Is A FEMA Buy-Out Property Being Impacted **No**

Environmental

Wetlands At Site None

Comments:

Endangered Species In County: **Bog Turtle, Carolina northern flying squirrel, Gray Bat, Northern Long eared bat, Appalachian elktoe, Mountain sweet pitcherplant, Small whorled pogonia, Spreading avens, Swamp pink, Virginia spiraea, Rock gnome lichen**

T&E species effect: No effect on all except NLEB-may affect, not likely to adversely affect.

Trout County : **Yes**

TVA County: **Yes**

CAMA County; **No**

Primary Nursery Area: **No**

Moratoria: **Yes**

Which species: **Brown Trout**

Duration : **Oct. 15 to April 15 no in-water**

Northern Long Ear Bat

May 15 to August 15, no tree clearing or bridge demolition

Permits discussion:

Water Quality Classification: **C; Tr, HQW**

303d: **No**

Coast Guard Permit? **No**

Drainage Basin: **French Broad**

Riparian Buffer Rules: **No**

Is The Project Site In Or Near Any Of The Following:

National Forest: **Yes**

Wildlife Refuge: **No**

State, County, Or Local Park: **No**

Wild And Scenic River: **No**

Airport: **No**

Recreation Of Power Generation: **No**

Water Supply Reservoir: **No**

Nutrient Sensitive Waters: **No**

Public Use Boat Ramp: **No**

Cemeteries: **No**

Known Or Potential Historic Properties In The Area:

Architecture: No Survey Required

Archaeology: No Sites Present

Is The Bridge Structure Itself, Or Any Part Thereof, Considered Historic: **No**

Impacts to a Church, Community Center, Or Other Public Facility? **No**

Is this a Statewide Bicycle Route or a Local Non-Marked Bicycle Route: **Yes – Route 5-Rosman to Blue Ridge Parkway**

Comments: **USFS to mark trees for pay out and DOT contractor will cut trees. Forest Service to do Biological Evaluation.**

Geotechnical

Are There Any Historical And/Or Vibration Sensitive Structures Near By **No**

Comments:

Are There Any Known Landfills And / Or Geo-environmental Hazard Sites At Or Within Close Proximity To The Project Site **No** Comments:

Are Any Impacts Anticipated To Natural Springs Or Artesian Wells: Comments:

Possible Foundation Type: @ **End Bents**

@ **Interior**

Hydraulics

FEMA Approval? **No** (MOA)

Is There Unusual Scour Potential? **No** Is Protection Needed? **Standard**

Are Banks Stable? **Yes** Is Protection Needed? **Standard**

Appreciable Amount Of Large Debris? **Moderate**

Placement Of Bents In The Water Be Allowed: **No** Where:

Superstructure Type: **Bridge** If Bridge: **CS** If girder; why?

Length Of Structure: **65'** Min. Number Of Spans: **1** Span Arrangement:

Waive offset: **No** Cap: **4'** Skewed:

Items To Be Discussed / Resolved At FSM By Attendees

Off-Site Stage: ☒ New Alignment: ☐ On-site detour ☐
Detour ☐

**Clear roadway width (CRW): 12' 10' lanes with
1' offsets each side**

Temp. Signals: Yes

Alignment: upstream or downstream

Environmental Document Prepared by DBE: Low Impact Data Spreadsheet ☒ Minimum Criteria Checklist ☐

ADT: **100 per SIR** NHS: **No** Tier: **Regional** Func. Class: **Major Collector- Rural**

Bridge Min. Clear Deck Width Recommended by Div.: **30' OTO with 2 bar metal rail (bike route)**

Roadway lane width **_10_'** with **_4_'** **paved** shoulders

Extension of Paved shoulders: **Project limits**

Pave to face of guardrail and taper 8:1 to travel lane/paved shoulder? **No**

Min. Pavement Surface Course: **2.5** inches: Existing Roadway: **21**

Pavement Marking: **Paint** Pavement markers: **None**

Will Railroad Involvement Be Required: **No** Method of Clearing: **II Modified**

Truck Percentage: **7 % per BIR (5% Duals and 2% TTST)** Reasonable Safe Speed per SIR: **25** mph

Liquidated damages: will be imposed after **210** days of closure/construction. Amt: \$ **500** per day

CEI by? **NCDOT** R/W by? **NCDOT** R/W monuments? **Yes. Concrete**

Salvageable materials: **Guardrail**

Contact Person/number: **Randy Ramsey – 828-692-3209**

Deliver to: **693 Mountain Road, Hendersonville, NC 28791**

Removal of previous structure remnant abutments/piers:

Sequencing priority in construction? **Do at same time as 870046 concurrently per Division**

Comments: **Provide weathered steel guardrail with wood posts. 2 bar anodized rail on bridge. Division requests 25' of new full depth each side of approach slab. On 4/28/2015, USFS stated access to Summey Cove trail can be closed during construction.**

