



- (B) WEATHERED ROCK: BIOTITE SCHIST
- (D) ARTIFICIAL FILL/RIP RAP: INFILLED WITH ALLUVIAL, VERY LOOSE TO MEDIUM DENSE, BROWN AND TAN, SILTY FINE TO COARSE SAND (A-3 AND A-2-4)
- (E) RESIDUAL: DENSE, BROWN, MICACEOUS, SAPROLITIC, SILTY, COARSE TO FINE SAND (A-2-4)
- (F) ALLUVIAL: SOFT, RED-BROWN, MICACEOUS, FINE SANDY CLAYEY SILT WITH GRAVEL (A-5)

NOTE: REFER TO BORING/CORING LOGS FOR MORE DETAILED DESCRIPTIONS



CROSS SECTION BENT 2	
BRIDGE 108 OVER LOWER BARTON'S CREEK ON SR 1834	
WAKE COUNTY	
Project No.: 8.2407901	Tip No.: B-3704
Federal No.: BRZ-1834 (2)	Vert. Scale: 1" = 10 FEET
Date: OCTOBER 2003	Horiz. Scale: 1" = 10 FEET
Drawn By: DJG	Drawing No.: 5