



- (B) WEATHERED ROCK: BIOTITE SCHIST
- (C) RESIDUAL: SOFT, BROWN, MICACEOUS, SAPROLITIC, COARSE TO FINE SANDY SILT (A-4)

NOTE: REFER TO BORING/CORING LOGS FOR MORE DETAILED DESCRIPTIONS



**CROSS SECTION BENT 1 (REVISED)**

BRIDGE 108 OVER LOWER BARTON'S CREEK ON SR 1834  
WAKE COUNTY

Project No.: 8.2407901	Tip No.: B-3704
Federal No.: BRZ-1834 (2)	Vert. Scale: 1" = 10 FEET
Date: OCTOBER 2003	Horiz. Scale: 1" = 10 FEET
Drawn By: DJG	Drawing No.: 4