

**B-3871**  
**Bridge No.64 on SR 1001 over Dog Branch**

HOLE #	SAMPLE #	PASS 10	PASS 40	PASS 200	CSESAND	FINESAND	SI	CL	LL	PI	CLASS	DEPTH	MOIST.	ORG.
B2-XB	SS-42	100	97	22	20.7	62	11.2	6.1	17	NP	A-2-4(0)	3.9-5.4	63.50%	
	SS-43	100	100	47	0.8	62	18.8	18.4	32	11	A-6(2)	13.4-14.9		
	SS-44	100	100	92	0.6	12.1	34.2	53.2	68	47	A-7-6(48)	23.4-24.9		
	SS-45	100	99	94	0.8	14.4	34.1	50.7	52	33	A-7-6(34)	78.4-79.9		
	SS-46	98	87	15	43.4	43.6	8.9	4.1	22	NP	A-2-4(0)	93.4-94.9		
	SS-47	100	99	59	2.4	42.2	18.9	36.5	47	30	A-7-6(14)	118.4-119.9		
	SS-48	100	98	75	3.9	46	23.7	26.4	38	17	A-6(12)	128.4-129.9		
	B1-XA	SS-100	100	98	13	8	82	5.9	4.1	23	NP	A-2-4(0)		
SS-101		100	100	43	0.2	65.2	14.3	20.4	29	7	A-4(0)	17.7-19.2		
SS-102		100	100	96	0.4	7.3	33.2	59.1	73	46	A-7-6(51)	22.7-24.2		
SS-103		95	80	35	27.5	38.1	14.1	20.4	40	21	A-2-6(2)	27.7-29.2		
SS-104		100	100	97	0.8	4.3	35.8	59.1	79	52	A-7-6(59)	37.7-39.2		
SS-105		100	99	94	0.8	16.3	34	48.9	53	34	A-7-6(35)	57.7-59.2		
SS-106		96	88	58	19.1	24.6	23.6	32.6	41	24	A-7-6(11)	77.7-79.2		
SS-107		96	83	19	43.2	38.5	10.2	8.1	24	NP	A-2-4(0)	92.7-94.2		
SS-108		100	94	34	24.6	44.8	16.3	14.3	28	9	A-2-4(0)	97.7-99.2		
SS-109		99	83	17	44	42.4	5.5	8.1	21	NP	A-2-4(0)	102.7-104.2		
SS-110		98	91	45	20.6	45.4	15.7	18.3	24	7	A-4(0)	112.7-114.2		