



SIDE VIEW NORTH FACE

ELEVATION WEST FACE



SIDE VIEW

SOUTH FACE



EAST FACE

+

+



PROPOSED REPAIR AREAS


SUBSTRUCTURE SPALL/DELAMINATION

__ DATE : <u>07-16</u> __ DATE : <u>07-16</u> J. H. DUKE DRAWN BY : ____
 CHECKED BY :
 S.L.CULLUM
 DATE :
 07-16

 DESIGN ENGINEER OF RECORD:
 S.L.CULLUM
 DATE :
 07-16

DocuSigned by:	CURR STATI				<u>re</u> co E no.		
Sanuel Cullun HOTH CARO	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
SEAL 043571	SUBSTRUCTURE CONC. REPAIR - BENT 9						
12/13/2016	REVISIONS					SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO.	BY:	DATE:	S-28	
FINAL UNLESS ALL	1		3			TOTAL SHEETS	
SIGNATURES COMPLETED	2		4				

PROJECT NO._



B-5937