


SIDE VIEW




+

+




PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION



\$\$\$\$\$\$YSTIME\$\$\$\$ \$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$DCN\$\$\$\$\$\$\$\$\$\$\$\$\$ \$\$\$\$USENNAME\$\$\$



PROJECT NO.__

B-5937