




SIDE VIEW

NORTH FACE



ELEVATION WEST FACE





SIDE VIEW SOUTH FACE

ELEVATION EAST FACE

+



PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION

 DRAWN BY :
 J.H.DUKE
 DATE :
 07-16

 CHECKED BY :
 S.L.CULLUM
 DATE :
 07-16

 DESIGN ENGINEER OF RECORD:
 S.L.CULLUM
 DATE :
 07-16
_____DATE : _____07-16 _____DATE : ____07-16

DocuSigned by: Sanuel Cullum	CURRITUCK/DARE COUNTY STATION: BRIDGE NO.16	
19697095C75A467	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEICH	
	SUBSTRUCTURE CONC. REPAIR - BENT 49	
12/13/2016	REVISIONS SHEET N	0.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	NO. BY: DATE: NO. BY: DATE: S-68 1 3	

