


SIDE VIEW

SOUTH FACE



EAST FACE

L ANTICIPATE CAP UNDERSIDE REPAIRS

+



DRAWN BY : ____

PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION

J. B. HANNA


 CHECKED BY :
 S.L.CULLUM
 DATE :
 07-16

 DESIGN ENGINEER OF RECORD:
 S.L.CULLUM
 DATE :
 07-16

_ DATE : <u>07-16</u> _ DATE : <u>07-16</u>

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONC.	Sanuel Cullum							
SEAL SUBSTRUCTURE CONC. 043571 SUBSTRUCTURE CONC. NGINE REPAIR - BENT 94 12/13/2016 REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL NO. BY: DATE: S-113 1 SUBSTRUCTURE CONC. 1 SHEET NO.	196970956755A467	DEPARTMENT OF TRANSPORTATION RALEIGH						
NO. BY: DATE: NO. BY: DATE: S-113 FINAL UNLESS ALL 1 3 SWEETS SWEETS	SEAL 043571							
FINAL UNLESS ALL 1 3	12/13/2016	REVISIONS SHEET NO.						
FINAL UNLESS ALL 1 3 JUNE	DOCUMENT NOT CONSTDERED	NO. BY:	DATE:		BY:	DATE:	S-113	
SIGNATURES COMPLETED 2 4	FINAL UNLESS ALL						TOTAL SHEETS	
	SIGNATURES COMPLETED	2		4				

PROJECT NO.



-DocuSigned by:



B-5937

CURRITUCK/DARE COUNTY STATION: BRIDGE NO. 16