



SIDE VIEW







SIDE VIEW


ELEVATION

+

+

SUBSTRUCTURE SPALL/DELAMINATION


PROPOSED REPAIR AREAS




\$\$\$\$\$\$YSTIME\$\$\$\$ \$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$DGN\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$ \$\$\$\$USERNAME\$\$\$\$

SUBSTRUCTURE CONC. REPAIR - BENT 110 SUBSTRUCTURE CONC. REPAIR - BENT 110 REVISIONS SHEET NO. S-129 FINAL UNLESS ALL SHEET NO. S-129 SHEET NO. SHEET NO. S-129 SHEET NO. S-129 SHEET NO. SHEET NO. SHEET NO. SHEET NO. S-129 SHEET NO. SHEET SHEET SHEET SHEET SHEET SHEET SHEET SHEET SHEET S	-19C97095C75A467	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONC. REPAIR - BENT 110						
DOCUMENT NOT CONSIDERED NO. BY: DATE: NO. BY: DATE: S-129 FINAL UNLESS ALL 1 3 3 JOTAL SPEETS	SEAL 043571							
FINAL UNLESS ALL 1 3	2/15/2010	REVISIONS						SHEET NO.
FINAL UNLESS ALL 1 3 SHEETS	OCUMENT NOT CONSTDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-129
		1			3			TOTAL SHEETS
SIGNATURES COMPLETED 🙎 🛛 🐴	SIGNATURES COMPLETED	2			4			

PROJECT NO.\_\_\_\_



-DocuSigned by: Sannel Cullun



B-5937

CURRITUCK/DARE COUNTY STATION: BRIDGE NO. 16