



WEST FACE



NORTH FACE



SIDE VIEW

ELEVATION

+



SUBSTRUCTURE SPALL/DELAMINATION

PROPOSED REPAIR AREAS

 DRAWN BY :
 J. B. HANNA
 DATE :
 07-16

 CHECKED BY :
 S. L. CULLUM
 DATE :
 07-16

 DESIGN ENGINEER OF RECORD:
 S. L. CULLUM
 DATE :
 07-16

\$\$\$\$\$\$YSTIME\$\$\$\$ \$\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$DGN\$\$\$\$\$\$\$\$\$\$\$\$\$\$\$ \$\$\$\$USERNAME\$\$\$\$

| DocuSigned by:                           |   |       |        |           |       |                 |
|--|---|-------|--------|-----------|-------|-----------------|
| Sanuel Cullun<br>19097095075A467         |   | STAT  | E OF   | NORTH CAR | OLINA |                 |
|  | DEPARTMENT OF TRANSPORTATION            |       |        |           |       |                 |
| 12/13/2016                               | SUBSTRUCTURE CONC.<br>REPAIR - BENT 135 |       |        |           |       |                 |
| 12/1 <del>3/201</del> 6                  | REVISIONS SHEET NO.                     |       |        |           |       |                 |
| DOCUMENT NOT CONSIDERED                  | NO. BY:                                 | DATE: | NO.    | BY:       | DATE: | S-154           |
| FINAL UNLESS ALL<br>SIGNATURES COMPLETED | 1<br>2                                  |       | 3<br>4 |           |       | TOTAL<br>SHEETS |

