

PROJECT NUMBER: 15BPR.46

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
N.C.	15BPR.46	1A	137
STATE PROJ. NO.	F.A. PROJ. NO.	DESCRIPTION	
15BPR.46	-	P.E.	
15BPR.46	-	CONST.	

KCA
KISINGER CAMPO
& ASSOCIATES
301 FAYETTEVILLE ST., SUITE 1500
RALEIGH, NC 27601
(919) 882-7839
LICENSE #: C-1506

INDEX OF SHEETS - STRUCTURES

1	TITLE SHEET	S-38	SUPERSTRUCTURE REPAIRS SPANS 49 THRU 52	S-77	SUBSTRUCTURE REPAIRS - BENT 12	S-116	SUBSTRUCTURE REPAIRS - BENT 51
1A	INDEX OF SHEETS	S-39	SUPERSTRUCTURE REPAIRS SPANS 53 THRU 56	S-78	SUBSTRUCTURE REPAIRS - BENT 13	S-117	SUBSTRUCTURE REPAIRS - BENT 52
S-1	BILL OF MATERIALS	S-40	SUPERSTRUCTURE REPAIRS SPANS 57 THRU 60	S-79	SUBSTRUCTURE REPAIRS - BENT 14	S-118	SUBSTRUCTURE REPAIRS - BENT 53
S-2	GENERAL DRAWING (1 OF 7)	S-41	SUPERSTRUCTURE REPAIRS SPANS 61 THRU 64	S-80	SUBSTRUCTURE REPAIRS - BENT 15	S-119	SUBSTRUCTURE REPAIRS - BENT 54
S-3	GENERAL DRAWING (2 OF 7)	S-42	SUPERSTRUCTURE REPAIRS SPANS 65 THRU 68	S-81	SUBSTRUCTURE REPAIRS - BENT 16	S-120	SUBSTRUCTURE REPAIRS - BENT 55
S-4	GENERAL DRAWING (3 OF 7)	S-43	SUPERSTRUCTURE REPAIRS SPANS 68 THRU 72	S-82	SUBSTRUCTURE REPAIRS - BENT 17	S-121	SUBSTRUCTURE REPAIRS - BENT 56
S-5	GENERAL DRAWING (4 OF 7)	S-44	SUPERSTRUCTURE REPAIRS SPAN 73	S-83	SUBSTRUCTURE REPAIRS - BENT 18	S-122	SUBSTRUCTURE REPAIRS - BENT 57
S-6	GENERAL DRAWING (5 OF 7)	S-45	JACKING DETAILS	S-84	SUBSTRUCTURE REPAIRS - BENT 19	S-123	SUBSTRUCTURE REPAIRS - BENT 58
S-7	GENERAL DRAWING (6 OF 7)	S-46	BEARING REPLACEMENT DETAILS	S-85	SUBSTRUCTURE REPAIRS - BENT 20	S-124	SUBSTRUCTURE REPAIRS - BENT 59
S-8	GENERAL DRAWING (7 OF 7)	S-47	BEARING REPLACEMENT DETAILS	S-86	SUBSTRUCTURE REPAIRS - BENT 21	S-125	SUBSTRUCTURE REPAIRS - BENT 60
S-9	TYPICAL SECTION SPANS 1-15 & 19-33	S-48	BEARING REPLACEMENT DETAILS	S-87	SUBSTRUCTURE REPAIRS - BENT 22	S-126	SUBSTRUCTURE REPAIRS - BENT 61
S-10	TYPICAL SECTION SPANS 16-18	S-49	2 BAR METAL RAIL	S-88	SUBSTRUCTURE REPAIRS - BENT 23	S-127	SUBSTRUCTURE REPAIRS - BENT 62
S-11	TYPICAL SECTION SPANS 34-73	S-50	2 BAR METAL RAIL	S-89	SUBSTRUCTURE REPAIRS - BENT 24	S-128	SUBSTRUCTURE REPAIRS - BENT 63
S-12	DECK SURFACE REPAIR - DETAILS	S-51	CONCRETE RESTORATION DETAILS	S-90	SUBSTRUCTURE REPAIRS - BENT 25	S-129	SUBSTRUCTURE REPAIRS - BENT 64
S-13	DECK SURFACE REPAIR 1-11	S-52	CONCRETE RESTORATION DETAILS	S-91	SUBSTRUCTURE REPAIRS - BENT 26	S-130	SUBSTRUCTURE REPAIRS - BENT 65
S-14	DECK SURFACE REPAIR 12-21	S-53	CONCRETE RESTORATION DETAILS	S-92	SUBSTRUCTURE REPAIRS - BENT 27	S-131	SUBSTRUCTURE REPAIRS - BENT 66
S-15	DECK SURFACE REPAIR 22-32	S-54	CONCRETE RESTORATION DETAILS	S-93	SUBSTRUCTURE REPAIRS - BENT 28	S-132	SUBSTRUCTURE REPAIRS - BENT 67
S-16	DECK SURFACE REPAIR 33-46	S-55	CATHODIC PROTECTION - BEAMS	S-94	SUBSTRUCTURE REPAIRS - BENT 29	S-133	SUBSTRUCTURE REPAIRS - BENT 68
S-17	DECK SURFACE REPAIR 47-60	S-56	CATHODIC PROTECTION - BEAMS	S-95	SUBSTRUCTURE REPAIRS - BENT 30	S-134	SUBSTRUCTURE REPAIRS - BENT 69
S-18	DECK SURFACE REPAIR 61-73	S-57	CATHODIC PROTECTION	S-96	SUBSTRUCTURE REPAIRS - BENT 31	S-135	SUBSTRUCTURE REPAIRS - BENT 70
S-19	APPROACH SLAB DETAILS	S-58	CATHODIC PROTECTION	S-97	SUBSTRUCTURE REPAIRS - BENT 32	S-136	SUBSTRUCTURE REPAIRS - BENT 71
S-20	JOINT DETAILS	S-59	CATHODIC PROTECTION	S-98	SUBSTRUCTURE REPAIRS - BENT 33	S-137	SUBSTRUCTURE REPAIRS - BENT 72
S-21	JOINT DETAILS	S-60	CATHODIC PROTECTION	S-99	SUBSTRUCTURE REPAIRS - BENT 34	S-	STANDARD NOTES
S-22	APPROACH ROADWAY	S-61	CATHODIC PROTECTION	S-100	SUBSTRUCTURE REPAIRS - BENT 35		
S-23	SUPERSTRUCTURE REPAIRS SPANS 1 THRU 3	S-62	CATHODIC PROTECTION	S-101	SUBSTRUCTURE REPAIRS - BENT 36		
S-24	SUPERSTRUCTURE REPAIRS SPANS 4 THRU 6	S-63	PILE NUMBERING SEQUENCE	S-102	SUBSTRUCTURE REPAIRS - BENT 37		
S-25	SUPERSTRUCTURE REPAIRS SPANS 7 THRU 9	S-64	END BENT 2 EROSION REMEDIATION	S-103	SUBSTRUCTURE REPAIRS - BENT 38		
S-26	SUPERSTRUCTURE REPAIRS SPANS 10 THRU 12	S-65	SUBSTRUCTURE REPAIRS - END BENTS 1 & 2	S-104	SUBSTRUCTURE REPAIRS - BENT 39		
S-27	SUPERSTRUCTURE REPAIRS SPANS 13 THRU 15	S-66	SUBSTRUCTURE REPAIRS - BENT 1	S-105	SUBSTRUCTURE REPAIRS - BENT 40		
S-28	SUPERSTRUCTURE REPAIRS SPANS 16 & 17	S-67	SUBSTRUCTURE REPAIRS - BENT 2	S-106	SUBSTRUCTURE REPAIRS - BENT 41		
S-29	SUPERSTRUCTURE REPAIRS SPANS 18 THRU 20	S-68	SUBSTRUCTURE REPAIRS - BENT 3	S-107	SUBSTRUCTURE REPAIRS - BENT 42		
S-30	SUPERSTRUCTURE REPAIRS SPANS 21 THRU 23	S-69	SUBSTRUCTURE REPAIRS - BENT 4	S-108	SUBSTRUCTURE REPAIRS - BENT 43		
S-31	SUPERSTRUCTURE REPAIRS SPANS 24 THRU 26	S-70	SUBSTRUCTURE REPAIRS - BENT 5	S-109	SUBSTRUCTURE REPAIRS - BENT 44		
S-32	SUPERSTRUCTURE REPAIRS SPANS 27 THRU 29	S-71	SUBSTRUCTURE REPAIRS - BENT 6	S-110	SUBSTRUCTURE REPAIRS - BENT 45		
S-33	SUPERSTRUCTURE REPAIRS SPANS 30 THRU 32	S-72	SUBSTRUCTURE REPAIRS - BENT 7	S-111	SUBSTRUCTURE REPAIRS - BENT 46		
S-34	SUPERSTRUCTURE REPAIRS SPANS 33 THRU 36	S-73	SUBSTRUCTURE REPAIRS - BENT 8	S-112	SUBSTRUCTURE REPAIRS - BENT 47		
S-35	SUPERSTRUCTURE REPAIRS SPANS 37 THRU 40	S-74	SUBSTRUCTURE REPAIRS - BENT 9	S-113	SUBSTRUCTURE REPAIRS - BENT 48		
S-36	SUPERSTRUCTURE REPAIRS SPANS 41 THRU 44	S-75	SUBSTRUCTURE REPAIRS - BENT 10	S-114	SUBSTRUCTURE REPAIRS - BENT 49		
S-37	SUPERSTRUCTURE REPAIRS SPANS 45 THRU 48	S-76	SUBSTRUCTURE REPAIRS - BENT 11	S-115	SUBSTRUCTURE REPAIRS - BENT 50		